

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Karl Houskeeper



Inspection Report

Permit Number:	C0150025		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, August 05, 2010		
Start Date/Time:	8/5/2010 6:30:00 AM		
End Date/Time:	8/5/2010 9:30:00 PM		
Last Inspection:	Wednesday, July 14, 2010		

Inspector: Karl Houskeeper,

Weather: Cloudy. Temp. 59 deg. F. InspectionID Report Number: 2447

> Accepted by: jhelfric 8/12/2010

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC

Site: BEAR CANYON MINE

Address: PO BOX 1240, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Ad	creages
------------	---------

	Total Permitted		
40.46	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface Loadout County Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Lynn McCourt Price Mine Service (PMS) was present during the inspection.

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

Date

Thursday, Augu

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Thursday, August 05, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	7		✓	
6.	Disposal of Excess Spoil, Fills, Benches	V	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	, 🗆			
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Thursday, August 05, 2010

Page 3 of 3

2. Signs and Markers

Mine identification sign is located on a fence at the point of public access to the permit area.

4.a Hydrologic Balance: Diversions

The majority of the diversions and culvert inlets and outlets have been recently maintained and cleaned following the recent storm events. A few diversions are still being worked on to remove rock and debris, but are still compliant with their approved design found in the Mining and Reclamation Plan (MRP).

4.c Hydrologic Balance: Other Sediment Control Measures

Some water is present in the sedimentation ponds from recent rain storm events.

5. Explosives

Explosives have been removed from the site. Magazines for caps and powder are still present along side of the access road to the portal area. The magazines are properly identified and grounded according to regulation.